



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>19 May 2022, 16:31:28</b>
Transaction Number	<b>53687595 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JN6FE52S87X422023</b>
Engine Number	
Vehicle Class	<b>Heavy</b>
Manufacturer	<b>Nissan</b>
Model	<b>Urvan</b>
Model Year	<b>2007</b>
Color	<b>White</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Odometer reading	NOT VISIBLE	قراءة عداد المسافات
01.B Other	GEAR SHIFTING LEVER DUST COVER DAMAGED	اخرى
01.C AC Condition	NOT COOLING & GRILL DAMAGED	المكيف
01.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
<b>02 Lights</b>		<b>الاضاءة</b>
02.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHE & PORTION RUSTY ,PORTION FADED	الصبغ
03.B Bumper	PORTION DAMAGED	دعامية
03.C Floor	REAR BACK PANEL DENT	الارضية
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	MINOR OIL LEAK & OPEN,REFITTED	حالة الجير النظرى
04.B Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Seat Condition	DAMAGED	حالة المقاعد
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Visual Engine Condition	REFITTED	حالة المحرك النظري
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	OK	الشاسيه
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Front Tyre	BOTH SIDE 2021/2022	الاطار الامامي
08.B Rear Tyre	LEFT SIDE 2019 CRACKED & RIGHT SIDE 2020	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.