




TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	03 Nov 2022, 12:52:53
Transaction Number	34193258 (CC10009)	Queue Number	617075



Chassis Number	JTEBX3FJ9EK156986
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Land Cruiser Prado
Model Year	2014
Color	White
Mileage	221808 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY TOTALLY REPAINTED EXCEPT ROOF,PORTION REPAIRED , MINOR DENTS SCRATCHES	الصبغ
01.B Bumper	MISALIGN	دعامية
01.C Bonnet	REFITTED	غطاء المحرك
01.D Fenders	FRONT REFITTED	مدكار
02 Interior Condition		الحالة الداخلية
02.A AC Condition	OK & REAR GRILL DAMAGED	المكيف
02.B Other	CENTER CENSOLE BOX LOCK NOT WORKING	اخرى
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2021,	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
04 Lights		الاضاءة
04.A Tail Light	REAR RIGHT SIDE TAIL LIGHT COVER DAMAGED	الانارة
05 Seats Condition		المقاعد
05.A Seat Condition	EXTRA COVER	حالة المقاعد

DEFECT	REMARKS	
06 Chassis Condition		الشاصي
06.A Chassis	CHASSIS FRAME THCIK RUST PROOFED , PORSTION MINOR RUSTY , OK	الشاشيه
07 Engine Condition		المحرك
07.A Mount	MOUNT RUBBER CRACKED	كرسي
07.B Smoke	BLACK SMOKE	دخان
07.C Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظري
08 Transmission Condition		الجير
08.A Visual Gear Box Condition	SIGN OF MINOR OIL LEAK REFITTED	حالة الجير النظري
08.B Road Test	NOT CHECK	فحص علي الطريق
09 Suspension System		ممتص الصدمات
09.A Other	STABILIZER LINK BOOT CUT	اخرى
09.B Arms	LOWER ARM BUSHES CUT	ازرع
09.C Ball Joint	BOOT CUT	مفصل كروي
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الروداد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.