

Queue Number

2810753

Transaction Date

29 Sep 2026, 13:23:05

Site Name

840 - Emirates Auctions

Transaction Number

58064099 (CC10009) (CC10012)



Vehicle Details

Chassis Number

WA1ZZZF9J*****

Specification

GCC Specification

Make

Audi

Model

Q5

Model Year

2018

Color

Grey

Mileage

325558 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY MINOR DENT SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Bumper	MISALIGN , REAR LEFT SIDE REFLECTOR CRACK	دعامية

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED MUDDY CHECKED VISIBLE AREA ONLY/OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK PARTS REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---------------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	REAR CENTER CAP COVER LOCK DAMAGED	حالة المقاعد
---------------------	------------------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	MINOR OIL LEAK PARTS REFITTED, GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

06 Tires and Rims Condition

الاطارات

06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي

Condition	Remarks	الحالة
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B AC Condition	NOT COOLING , REAR GRILL DAMAGED	المكيف
09.C Roof Ceiling	PORTION LOOSE	بطانه السقف
09.D Door Panel	PORTION LOOSE	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.F Sunroof	NOT WORKING , CURTAIN DAMAGED	فتحت سقف
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	SIGN OF OIL MIXED	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae