





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 19980809	Plate Category	: PRIVATE
Transaction Date	: 16 JUN 2020 12:37:19	Plate Number	: 653 EA
Queue Number	: 186338	Import Doc. Ref.	:
Chassis Number	: WBAFG81009L282653	Manufacturer/Model	: BMW/X6
Engine Number	:	Model Year	: 2009
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.04 - Steering Ball Joints, Boots		وصلات عمود عجلة القيادة
		FRONT RIGHT STEERING BOOT CRACK
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
		BRAKE ROTORS RUSTY
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		ALL TIRES DOT 2017
04.07 - Rims		الرنجات
		SCRATCHES
05 Body		الهيكل
05.02 - Paint		الصبغ
		BODY SCRATCHES & DENTS
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
		FRONT WINDSHIELD REPLACED
06 General Items		الاشياء العامة
06.01 - Wiper Blades		ماسحات الزجاج الامامي
		WORN OUT
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
		INTERIOR PARTLY WORN OUT
06.14 - Transmission Condition		حالة ناقل الحركة
		OK
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		OK
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		151027 KMS / BONNET DAMPER WEAK / GRILLE LOOSE/ FR & RR DIFF OIL STAINS
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.06 - Chassis Ok		الشاصي جيد
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.25 - Body Repainted		أثر صبغ في المركبة
		BODY PORTIONS REPAINTED



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 19980809	Plate Category	: PRIVATE
Transaction Date	: 16 JUN 2020 12:37:19	Plate Number	: 653 EA
Queue Number	: 186338	Import Doc. Ref.	:
Chassis Number	: WBAFG81009L282653	Manufacturer/Model	: BMW/X6
Engine Number	:	Model Year	: 2009
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

The Test Certificate Shows the test Result at the time of inspection only.