CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2919601
Transaction Date	28 Oct 2026, 16:42:23
Site Name	840 - Emirates Auctions
Transaction Number	31822140 (CC10013) (CC10019)



Vehicle Details

Chassis Number	3N6DD23Y8E*******
Specification	GCC Specification
Make	Nissan
Model	2400
Model Year	2014
Color	White
Mileage	261060 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY,REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES.PORTION RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUST PROOFED BODY MOUNT RUBBER DRY CRACK	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Vehicle Model	PICK-UP / NP2400	طراز المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME RUST PROOFED PORTION DENT GETTING RUSTY MUDDY	الشاسيه
02.B Chassis Number	VIN CHECK DOOR POST PLATE	رقم القاعدة
03 Engine Condition		المحرك
03.A Mount	MOUNT RUBBER DRY CRACK	كرسي
03.B Engine Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الخلفي
06.C Spare Tire &Tools	MISSING	الاطار الاحتياطي و العدة
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	MINOR LEAK	ممتص الصدمات
08.B Leaf Spring	MISALIGN , BUSHES DRY CRACK	
08.C Arms	ARM BUSHES DRY CRACK	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخري
09.B AC Condition	OK,GRILL PORTION DAMAGED	المكيف
09.C Dash Board	PORTION FADED	لوحة القياده
09.D Roof Ceiling	REAR BOTH SIDE GRAB HANDLE MISSING	بطانه السقف
09.E Sun Visor	LEFT SIDE PORTION LOOSE	حاجب الشمس
09.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae