



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>17 May 2022, 12:39:33</b>
Transaction Number	<b>78011413 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>MR1DX8FS8H0009106</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Fortuner</b>
Model Year	<b>2017</b>
Color	<b>Red</b>
Mileage	<b>197070 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
01.B Rear Tyre	RIGHT SIDE 2020 .LEFT SIDE 2016 EXPIRED	الاطار الخلفي
<b>02 Seats Condition</b>		<b>المقاعد</b>
02.A Seat Condition	SEAT REAR MISSING	حالة المقاعد
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Trunk	REFITTED	صندوق
03.B Paint	BODY TOTALLY REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES ON BODY ( VEHICLE COLOUR CHANGED FROM WHITE TO SILVER)	الصبغ
03.C Bonnet	REFITTED	غطاء المحرك
03.D Fenders	REFITTED	مدكار
03.E Other	(VEHICLE CURRENT COLOUR SILVER)	اخرى
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A AC Condition	OK	المكيف
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>

DEFECT	REMARKS	
05.A Arms	BOTH SIDE LOWER ARM BUSHES MINOR CRACKED	ازرع
05.B Ball Joint	BOOT CUT	مفصل كروي
<b>06 Steering Condition</b>		<b>المقود</b>
06.A Tie Rod End	BOOT CUT	مؤخرة الروداد
06.B Other	STABILIZER LINK BOOT CUT	اخرى
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	OK	الشاسيه
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08.B Head Light	BOTH SIDE LOWE HIGH BEAM NOT WORKING	الاضاءة الرئيسية
<b>09 Battery Condition</b>		<b>حالة البطارية</b>
09.A Battery bracket	LOOSE	حامل البطارية
<b>10 Transmission Condition</b>		<b>الجير</b>
10.A Road Test	NOT CHECK	فحص علي الطريق
10.B Visual Gear Box Condition	OK	حالة الجير النظري
10.C Gear Box Mount	MOUNT RUBBER MINOR CRACKED	كرسي الجير
<b>11 Engine Condition</b>		<b>المحرك</b>
11.A Visual Engine Condition	OK	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.