

Queue Number	2815348	Transaction Date	30 Sep 2026, 14:39:21
Site Name	840 - Emirates Auctions	Transaction Number	18126184 (CC10013) (CC10025)



Vehicle Details

Chassis Number	4P3XTGA2WF*****
Specification	GCC Specification
Make	Mitsubishi
Model	ASX
Model Year	2015
Color	Silver
Mileage	102706 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body		جسم المركبة
01.A Fenders	FRONT FIBER , REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED , EXCEPT ROOF TRUNK , MINOR DENT SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION MINOR DENT	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Trunk	SHOCK WEAK	صندوق
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OK	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص على الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES SIGN OF MINOR CRACK	ازرع
08 Interior Condition		الحالة الداخلية
08.A Other	CENTER CONSOLE BOX PORTION DAMAGED LOOSE , INTERIOR PARTS GETTING RUSTY	اخرى
08.B Odometer reading	DISPLAY PORTION FADED	قراءة عداد المسافات
08.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.D Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae