CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877823
Transaction Date	19 Oct 2026, 17:42:20
Site Name	840 - Emirates Auctions
Transaction Number	43218815 (CC10006) (CC10006)



Vehicle Details

Chassis Number	2C3CDXGJ3J*******
Specification	Imported
Make	Dodge
Model	Charger
Model Year	2018
Color	Blue
Mileage	126272 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION COVER , PORTION REPAIRED ,QUARTER PANEL REPAIRED	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.E Bonnet	STAY SHOCK WEAK , NOT WORKING	غطاء المحرك
01.F Pillars	LEFT SIDE DOOR PILLAR , ROCKER PANEL , RUNNING BOARD , FIRE WALL AREA , WHEEL ARCH REPAIRED	القوائم
01.G Sign of front accident	FRONT BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME, APRON REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED , BEND	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED SIGN OF OIL WET . PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Exhaust System		نظام العادم

Condition	Remarks	الحالة
05.A Modification	EXHAUST PIPE CUT REWELDED	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	NOT CHECKED REFITTED SIGN OF OIL WET PARTS GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	LEFT SIDE 2023 WORN OUT CRACK & RIGHT SIDE 2024 CRACK	الاطار الامامي
07.B Rear Tyre	LEFT SIDE 2024 & RIGHT SIDE 2022 CRACK DAMAGE	الاطار الخلفي
07.C Rims Condition	DENT SCRATCHES	حالة الجنوط
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACK	ازرع
09.B Stabilizer Bar And Link Rod	BOOT CRACK	عمود التوازن و مثبت عمود التوازن
10 Interior Condition		الحاله الداخليه
10.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
10.B AC Condition	NOT CHECK	المكيف
10.C Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.D Door Panel	PORTION DAMAGE	لوحة بطانة الباب
10.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
10.G Engine Start Button	REMOTE PORTION WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae