CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877703
Transaction Date	17 Oct 2026, 11:33:56
Site Name	840 - Emirates Auctions
Transaction Number	45333159 (CC10021) (CC10019)



Vehicle Details

Chassis Number	3VWCB21C92*******
Specification	Imported
Make	Volkswagen
Model	Beetle
Model Year	2002
Color	Yellow
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES ,PORTION RUSTY PORTION FADED .	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	PORTION DENT	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED.	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED,MUDDY,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي

Condition	Remarks	الحالة
06.B Rear Tyre	BOTH SIDE 2024 CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS RUSTY WATER FLOODED	اخري
09.B AC Condition	NOT CHECKED	المكيف
09.C Audio	MISSING	صوتيات
09.D Dash Board	PORTION DAMAGED,FADED	لوحة القياده
09.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
09.F Door Panel	PORTION DAMAGED.LOOSE	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	DUST COVER WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae