

Queue Number

2793355

Transaction Date

24 Sep 2026, 16:02:24

Site Name

840 - Emirates Auctions

Transaction Number

27415747 (CC10008) (CC10025)



Vehicle Details

Chassis Number	JTEHJ09J81*****
Specification	GCC Specification
Make	Toyota
Model	Land Cruiser
Model Year	2001
Color	Black
Mileage	307718 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصيغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Bumper	MISALIGN	دعامية
01.D Bonnet	SHOCK NOT WORKING	غطاء المحرك
01.E Trunk	SHOCK WEAK ,LEFT SIDE CABLE DAMAGED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION GETTING RUSTY /OK	الشاسيه
--------------	-----------------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK .REFITTED,PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	OIL LEAK ,REFITTED ,PARTS GETTING RUSTY	الحالة النظرية للجير
05.B DIFFERENTIAL	FRONT MINOR OIL LEAK	الدفرنشيل
05.C Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	RIGHT SIDE BRACKET DAMAGED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE PORTION CRACK	الضوء الخلفي
08 Steering Condition		المقود
08.A Steering Oil	OIL LEAK	زيت المقود
08.B Axle	FRONT GREASE LEAK	اكسلات
09 Interior Condition		الحالة الداخلية
09.A Other	CENTER CONSOLE BOX COVER WORN OUT PORTION LOOSE CUP HOLDER LOCK COVER DAMAGED , INTRIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخرى
09.B Mirror	RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY	المرآيا
09.C AC Condition	OK	المكيف
09.D Dash Board	WORN OUT , PORTION CRACK	لوحة القيادة
09.E Door Panel	WORN OUT , PORTION CRACK	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae