CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 2906138 |
| Transaction Date | 27 Oct 2026, 15:17:28 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 61895324 (CC10010) (CC10011) |




**Vehicle Details**

| | |
|---|---|
| Chassis Number | 4T1BE30K42******* |
| Specification | Imported |
| Make | Toyota |
| Model | Camry |
| Model Year | 2002 |
| Color | Black |
| Mileage | 380352 Miles |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 4 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Fenders | FRONT REFITTED | مدكار |
| 01.B Paint | BODY REPAINTED,PORTION REPAIRED,DENTS SCRATCHES,PORTION FADED RUSTY | الصبغ |
| 01.C Rusty | UNDER BODY SUSPENSION PARTS GETTING RUSTY. | صدأ |
| 01.D Floor | UNDER FLOOR PORTION DENT ,MUDDY., | الارضية |
| 01.E Bumper | MISALIGN,PORTION DAMAGED | دعامية |
| 01.F Bonnet | REFITTED | غطاء المحرك |
| 01.G Pillars | PILLAR OUTER PANEL DENT | القوائم |
| 01.H Door Handle &Lock | INNER HANDLE DAMAGED. | مقابض الأبواب والأقفال |
| 01.I Sign of front accident | FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED. | وجود مؤشر لحادث في المقدمة |
| 01.J Sign of back accident | BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED. | وجود مؤشر لحادث في الخلف |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | REAR EXTENSION END ,FRONT CHASSIS END DENT GETTING RUSTY. | الشاسيه |
| 02.B Chassis Number | VIN STICKER PORTION LOOSE . | رقم القاعدة |
| **03 Engine Condition** | | المحرك |
| 03.A Engine Visual Condition | ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY | الحالة النظريه للمحرك |
| **04 Seats Condition** | | المقاعد |

| Condition | Remarks | الحالة |
|---|---|---|
| 04.A Seat Condition | PORTION DAMAGED | حالة المقاعد |
| **05 Transmission Condition** | | الجير |
| 05.A Gear Box Visual Condition | NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY . | الحالة النظريه للجير |
| 05.B Road Test | NOT CHECKED. | فحص علي الطريق |
| **06 Tires and Rims Condition** | | الاطارات |
| 06.A Front Tyre | BOTH SIDW 2023 CRACKED | الاطار الامامي |
| 06.B Rear Tyre | BOTH SIDE 205/2026 DRY CRACKED | الاطار الخلفي |
| **07 Lights** | | الاضاءة |
| 07.A Head Light | LENS FADED ALL LIGHTS NOT CHECK | الاضاءة الرئيسية |
| **08 Brake Condition** | | الفرامل |
| 08.A Disc&Drum | RUSTY | دسك وطنابير الفرامل |
| **09 Suspension System** | | ممتص الصدمات |
| 09.A Shock Absorber | LEAK. | ممتص الصدمات |
| 09.B Arms | BUSHES CUT . | ازرع |
| 09.C Stabilizer Bar And Link Rod | WORN OUT. | عمود التوازن و مثبت عمود التوازن |
| **10 Steering Condition** | | المقود |
| 10.A Steering Boot | CUT . | ربلة المقود |
| 10.B Steering Box | OIL LEAK . | جهاز المقود |
| **11 Interior Condition** | | الحاله الداخليه |
| 11.A Other | CUP HOLDER COVER DAMAGED MISSING,REAR DAMAGED | اخري |
| 11.B Mirror | COVER PORTION CRACKED | المرايا |
| 11.C AC Condition | NOT CHECK,GRILL PORTION DAMAGED | المكيف |
| 11.D Roof Light | FRONT MISSING | أنارة السقف |
| 11.E Dash Board | PORTION CRACKED | لوحة القياده |
| 11.F Roof Ceiling | LOOSE | بطانه السقف |
| 11.G Sun Visor | LEFT SIDE LOOSE | حاجب الشمس |
| 11.H Door Panel | PORTION WORN OUT DAMAGED | لوحة بطانة الباب |
| 11.I Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 11.J Gear Shifting Lever | KNOB WORN OUT,PANEL PORTION DAMAGED | ذراع نقل السرعات |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**