

Queue Number 2815065

Transaction Date 29 Sep 2026, 16:41:17

Site Name
840 - Emirates AuctionsTransaction Number
25858216 (CC10013) (CC10011)

Vehicle Details

Chassis Number	1G6D91E37D*****
Specification	GCC Specification
Make	Cadillac
Model	CTS
Model Year	2013
Color	Black
Mileage	237874 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Paint	BODY REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES	الصبغ
01.B Doors	REFITTED	أبواب
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUST PROOFED REINFORCEMENT DENTS	الارضية
01.E Bumper	MISALIGN , PORTION CRACK , REAR BUMPER FIXS BY SCREW,TOWING HOOK COVER MISSING	دعامية
01.F Bonnet	MISALIGN , REFITTED	غطاء المحرك

02 Chassis Condition الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS LOADING POINT PORTION GETTING RUSTY / REAR LEFT SIDE EXTENSION LOWER EDGE MINOR DENT / PORTION RUST PROOFED	الشاسيه
--------------	---	---------

03 Engine Condition المحرك

03.A Other	UPPER COVER MISSING	اخرى
03.B Engine Visual Condition	MINOR OIL LEAK , COMPONENTS REPAINTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك

04 Seats Condition المقاعد

04.A Seat Condition	PORTION CRACK DAMAGE , DRIVER SEAT PLAY	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL WET , COMPONENTS REPAINTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACK GETTING WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Other	BOTTLE CAP MISSING	اخرى
08 Lights		الاضاءة
08.A Tail Light	PORTION CRACK	الضوء الخلفي
08.B Brake Light	BRAKE LIGHT CENTER HOUSING CRACK	نور الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
10 Interior Condition		الحالة الداخلية
10.A Other	CENTER CONSOLE BOX COVER DAMAGE , INTERIOR PARTS GETTING RUSTY	اخرى
10.B Mirror	BOTH SIDE VIEW MIRROR AUTO FOLDING NOT WORKING, RIGHT SIDE LOOSE	المرآيا
10.C AC Condition	OK	المكيف
10.D Audio	LCD FADED,FOLDING NOT WORKING	صوتيات
10.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
10.F Gear Shifting Lever	KNOB PORTION WORN OUT	ذراع نقل السرعات
10.G Engine Start Button	REMOTE PORTION FADED	زر تشغيل المحرك
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	WATER MIX WITH OIL / WATER LEVEL LOW	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae