CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2978017
Transaction Date	12 Nov 2026, 13:06:45
Site Name	840 - Emirates Auctions
Transaction Number	68154269 (CC10009) (CC10019)



Vehicle Details

Chassis Number	1N4BL4CV2L*******
Specification	Imported
Make	Nissan
Model	Altima
Model Year	2020
Color	Grey
Mileage	165559 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,PORTION FADED	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR RUNNING BOARD REPAIRED	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Pillars	RIGHT SIDE A/ LEFT SIDE C/ PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Sign of front accident	FRONT BUMPER FRAME BULK HEAD FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED SUSPECT REPLACED, REAR LEFT SIDE CHASSIS INNER SIDE CROSS MEMEBR BEND	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK PARTS REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY MINOR JERKING	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		**الاضاءة**
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Fog light	NOT WORKING	كشاف الضباب
07 Suspension System		**ممتص الصدمات**
07.A Suspension Subframe	FRONT BEND	
07.B Arms	BUSHES CRACKED REAR LEFT SIDE ARM BEND	ازرع
08 Interior Condition		**الحاله الداخليه**
08.A Other	INETRIOR PARTS RUSTY,WATER FLOODED	اخري
08.B AC Condition	OK	المكيف
08.C Dash Board	LEATHER REPLACED.	لوحة القياده
08.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.E Air Bag	REFITTED	وسائد هوائية
08.F Gear Shifting Lever	KNOB WORN OUT LOOSE	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae