

Queue Number 2773310

Transaction Date 21 Sep 2026, 16:03:46

Site Name
840 - Emirates AuctionsTransaction Number
13188531 (CC10013) (CC10013)

Vehicle Details

Chassis Number	5FNRL38228*****
Specification	Imported
Make	Honda
Model	Odyssey
Model Year	2008
Color	Grey
Mileage	243082 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED, PORTION REPAIRED, DENTS, SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED LOGO MISSING	دعامية
01.E Windshield	FRONT CRACKED	زجاج
01.F Fuel Tank	DENT / LEAK	خزان الوقود

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS MUDDY OILY DIRTY PORTION GETTING RUSTY	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Other	INNER COMPARTMENT WIRING UNSAFE SIGN OF BURNING / ACCELERATOR NOT WORKING PROPERLY	اخرى
03.B Engine Visual Condition	MISFIRING , SHAKING , REFITTED , PARTS GETTING RUSTY , OIL LEAK	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
---------------------	------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR JERKING , REFITTED , OIL LEAK , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2023 DRY CRACK	الاطار الامامي
06.B Rear Tyre	2023 DRY CRACK	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED, BRACKET DAMAGED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طناير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	LOWER ARM BUSHES CUT	ازرع
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	NOT WORKING	المكيف
10.C Dash Board	GETTING FADED PORTION WORN OUT CRACK	لوحة القيادة
10.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae