CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3004153
Transaction Date	18 Nov 2026, 13:15:35
Site Name	840 - Emirates Auctions
Transaction Number	81806903 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JN8AY2NY7E*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2014
Color	Black
Mileage	430546 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,EXCEPT TRUNK,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY MUDDY	صدأ
01.D Floor	UNDER FLOOR MUDDY DITRY MOUNT RUBBER DRY CRACK	الارضية
01.E Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.F Bonnet	STAY SHOCK NOT WORKING / REFITTED	غطاء المحرك
01.G Trunk	NOT OPEN FOR CHECK / REAR SWITCH DAMAGED	صندوق
01.H Fuel Tank	DENT	خزان الوقود
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME GETTING RUSTY PORTION MINOR BULGED	الشاسيه
03 Engine Condition		المحرك
03.A Other	INNER COMPARTMENT ELECTRIC WIRING WORN OUT UNSAFE	اخري
03.B Engine Visual Condition	OIL PAN DENT , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	GEAR FAULT , NOT SHIFTING PROPERLY , WHILE DRIVE NOISY , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2024 DRY CRACK	الاطار الامامي
06.B Rear Tyre	2024 DRY CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DNET SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE PORTION CRACK	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES DRY CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY REFITTED,REAR CUP HOLDER DAMAGED	اخري
11.B Mirror	RIGHT SIDE VIEW MIRROR FOLDING NOT WORKING	المرايا
11.C AC Condition	OK , GRILL PORTION WORN OUT	المكيف
11.D Roof Light	PANEL LOOSE	أنارة السقف
11.E Power Window Switch And Glass	FRONT RIGHT & REAR BOTH SIDE NOT WORKING	مفتاح النافذه و الزجاج
11.F Dash Board	GETTING FADED PORTION WORN OUT MALTED	لوحة القياده
11.G Sun Visor	LEFT MISSING	حاجب الشمس
11.H Door Panel	PORTION DAMAGED	لوحة بطانة الباب
11.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.J Gear Shifting Lever	KNOB & DUST WORN OUT DAMAGED	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	WATER EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae