

Queue Number 2827646

Transaction Date 07 Oct 2026, 13:18:53

Site Name
840 - Emirates AuctionsTransaction Number
47771248 (CC10010) (CC10010)

Vehicle Details

Chassis Number 1N4AL3AP2F*****
 Specification GCC Specification
 Make Nissan
 Model Altima
 Model Year 2015
 Color Silver
 Mileage 268947 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED PORTON RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR MUDDY, PORTION DENTS	الارضية
01.E Bumper	MISALIGN SCRATCHES .	دعامية
01.F Bonnet	REFITTED ,REPAINTED .	غطاء المحرك
01.G Sign of front accident	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT CHASSIS COVERED OILY MUDDY ,PORTION RUSTY ,PORTION DENT .	الشاسيه
02.B Other	STEAM WASH CHASSIS FOR INSPECTION .	اخرى

03 Engine Condition

المحرك

03.A Mount	BUSHES CRACKED.	كرسي
03.B Smoke	MINOR WHITE.	دخان
03.C Engine Visual Condition	PARTS REFITTED ,COMPONENT PARTS RUSTY SHAKING ABNORMAL NOISY .	الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	COMPONENT PARTS RUSTY GET JERKING.	الحالة النظرية للجير
--------------------------------	------------------------------------	----------------------

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE EXPIRED CRACKED WORN OUT .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE EXPIRED CRACKED WORN OUT .	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED.	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT ON IN INSTRUMENT CLUSTER.	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY.	دواسة الفرامل
07.B Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CRACKED .	ربلة المقود
09.B Steering Box	OIL LEAK ,HARD .	جهاز المقود
10 Interior Condition		الحالة الداخلية
10.A Other	UNDER SEATS ,INTERIOR METAL PARTS RUSTY, WATER FLOODED	اخرى
10.B AC Condition	NOT COOLING.	المكيف
10.C Power Window Switch And Glass	FRONT RIGHT SIDE NOT WORKING.	مفتاح النافذه و الزجاج
10.D Roof Ceiling	PORTION LOOSE.	بطانه السقف
10.E Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT.	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات
11 Battery Condition		حالة البطارية
11.A Battery Condition	MISSING.	حالة البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae