



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	20 Nov 2022, 16:50:33
Transaction Number	82221042 (CC10009)	Queue Number	626470



Chassis Number	1ZVBP8AM1D5273555
Engine Number	
Vehicle Class	Car
Manufacturer	Ford
Model	Mustang
Model Year	2013
Color	Black
Mileage	50117 Miles
Fuel Type	Petrol
No. Of Cylinders	6
Specification	Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Other	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED	اخرى
01.B Paint	REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES & VEHICLE COLOR BLUE ,BLACK	الصبغ
01.C Fenders	FRONT FENDER REFITTED & REAR FENDER REPAIRED,REPAINTED	مدكار
01.D Sign of front accident		وجود مؤشر لحادث في المقدمة
01.E Pillars	BOTH SIDE B/PILLAR ,ROCKER REPAIRED	القوائم
01.F Sign of side accident		وجود مؤشر لحادث في الجانب
02 Engine Condition		المحرك
02.A Visual Engine Condition	OIL LEAK REFITTED	حالة المحرك النظري
02.B Other	START SWITCH PANLE LOOSE	اخرى
03 Suspension System		ممتص الصدمات
03.A Arms	LOWER ARM BUSHES CUT	ازرع
03.B Other	STABILIZER LINK BOOT CUT	اخرى
03.C Ball Joint	BOOT CUT	مفصل كروي

DEFECT	REMARKS	
04 Steering Condition		المقود
04.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
04.B Steering Oil	SIGN OF MINOR OIL LEAK	زيت المقود
05 Transmission Condition		الجير
05.A DIFFERENTIAL	REAR MINOR OIL LEAK	الدفرنشئل
05.B Visual Gear Box Condition	REFITTED	حالة الجير النظري
05.C Road Test	NOT CHECKED	فحص علي الطريق
05.D Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
06 Chassis Condition		الشاصي
06.A Chassis Number	MANUFACTUR STICKER MISSING	رقم القاعدة
06.B Chassis	FRONT BOTH SIDE CHASSIS REPAIRED	الشاسيه
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
08 Seats Condition		المقاعد
08.A Other	DRIVER SEAT ADJUSTMENT LEVER MISSING	اخرى
09 Interior Condition		الحاله الداخليه
09.A Other	GEAR LEVER KNOB DAMAGED	اخرى
10 Exhaust System		نظام العادم
10.A Modification	MODIFIED NOISY	تعديلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Transfer Certificate :	66413292
Chassis No :	1ZVBP8AM1D5273555
Vehicle Make :	FORD
Vehicle Model :	MUSTANG
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	Blue, Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	80653 Kms.
Origin : United States	Model Year : 2013
Gear Type : Manual	Engine Size : 3600 CC
Engine No : NIL	Horse 305
Axles No : 2	Power :
No Of 2	Cylinders : 6
Doors :	No Of Seats : 4
G. V. W. : 1890 Kgs.	Empty 1626 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-18114978		
Inspection Date :	16-11-2022		
Certificate Print Date :	16-11-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	5 min 51 sec		
Appointment Ref Number :	--		
Start Time :	15:45	End Time :	15:51
Lane :	03	Token No. :	215
Attempt :	2	Prints No :	1

Inspection Findings

Defects	Issue	Severity
Warning triangle	Missing	Major
Exhaust pipes and silencers muffler FIX ORIGNAL	Noisy	Major
Gear/Differential FIX GEAR LEVER NOBE DAMAGED	Others (Major)	Major
Engine REPAIR OIL LEAK AND WASH PROPERLY	Others (Major)	Major
Rim REMOVE FANCY WHEEL NUTS FIX ORIGNAL	Others (Major)	Major

Inspection Remarks:

front left side chassis repaired ccm ok , workorder-2022-11-16-2/FRONT BULK HEAD , RAD FRAME BUMBER SUPPORT REAR BACK PANEL REPAIRED.

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
34600	Cash	18114978	AED 70 Collected on 16/11/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	2	Bajurdeen Abdul Gafoor

i This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

i Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

