



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	23 Jun 2022, 15:43:36
Transaction Number	69285669 (CC10008)	Queue Number	312309



Chassis Number	MROCX8CD4H0692833
Engine Number	
Vehicle Class	Heavy
Manufacturer	Toyota
Model	Hilux
Model Year	2017
Color	White
Mileage	128590 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Doors	FRONT LEFT SIDE & REAR BOTH SIDE PORTION REPAIRED,REPAINTED	أبواب
01.B Fenders	REAR CARRIOR BOX PORTION REPAIRED,REPAINTED	مدكار
01.C Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
01.D Sign of back accident		وجود مؤشر لحادث في الخلف
01.E Pillars	RIGHT SIDE C/PILLAR OUTER PANEL REPAIRED	القوائم
02 Engine Condition		المحرك
02.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري
03.B Road Test	NOT CHECK	فحص علي الطريق
04 Steering Condition		المقود
04.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
05 Tires and Rims Condition		الاطارات

DEFECT	REMARKS	
05.A Front Tyre	LEFT SIDE 2017 CRACKED , EXPIRED & RIGHT SIDE 2019 MINOR CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
06 Chassis Condition		الشاسي
06.A Chassis	OK	الشاسيه
07 Interior Condition		الحاله الداخليه
07.A AC Condition	OK	المكيف
08 Suspension System		ممتص الصدمات
08.A Ball Joint	BOOT CUT	مفصل كروي
08.B Other	STABILIZER LINK BOOT CUT	اخرى
08.C Arms	FRONT LOWER ARM BUSH CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.