



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20262899	Plate Category	: PRIVATE
Transaction Date	: 16 JUL 2020 12:22:46	Plate Number	: 405982 EA
Queue Number	: 196727	Import Doc. Ref.	:
Chassis Number	: JHMFD16208S405982	Manufacturer/Model	: HONDA/CIVIC
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Failed	فحص ميزانية الاطارات
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.03 - Steering Wheel, Change, Repair		مقبض عجلة القيادة
		STEERING & BODY VIBRATION & STEERING WHEEL OFF CENTER
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		TIRES WORN OUT
05 Body		الهيكل
05.03 - Doors		الابواب
		REAR LEFT SIDE DOOR PILLAR & QUARTER PANEL REPAIRED
05.07 - Floor		الارضية
		REAR COMPARTMENT /BACK PANEL REPAIRED
05.08 - Chassis (Frame)		الشاصية
		REAR BOTH SIDE FRAME MEMBER REPAIRED
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		82245 KM
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		يحتاج الى ميزانية العجلات
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.25 - Body Repainted		أثر صيغ في المركبة
		BODY PORTION REPAINTED

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

Test Certificate



PASS

Possession Certificate :	64341269
Chassis No :	JHMF16208S405982
Vehicle Make :	HONDA
Vehicle Model :	CIVIC
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	82246 Kms.
Origin :	Japan
Model Year :	2008
Gear Type :	--
Engine No :	R18A130164...
Engine Size :	1800 CC
Axles No :	2
No Of Doors :	4
G. V. W. :	1850 Kgs.
Cylinders :	4
No Of Seats :	5
Empty Weight :	1200 Kgs.
Horse Power :	140

Certificate Number :	5-TAS-2020-12182213
Inspection Date :	19-07-2020
Certificate Print Date :	19-07-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	11 min 18 sec
Appointment Ref Number :	--
Start Time :	10:05
End Time :	10:16
Lane :	01
Token No. :	3
Attempt :	1
Prints No. :	1

Carbon footprint



0.1 ton

4

5

12+

ton CO2

Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



156 KM

Distance per
year



12 L

Fuel consumed
per year



20 AED

Fuel cost per
year



0.1 ton

Carbon footprint
per year

Parameter Readings

Service brake imbalance on
front axle
5 %

Service brake imbalance on
rear axle
7 %

Parking brake imbalance
between LHS and RHS
31 %

Vehicle on Petrol CO Reading
0.01 %

Vehicle on Petrol HC Reading
1 PPM VOL

Inspection Remarks:

REAR LEFT SIDE C/PILLAR,WHEEL ARC&QUARTER PANEL,COMPARTMENT FLOORING & RUNNING BOARD // REAR LEFT SIDE FRAME MEMBER . REPAIRED/. CCM WORK ORDER # 20200702-15

Payment Details

Inspection Performed by
59460

Parking Slot No
--

Payment Method
VTP Credit Account

Service Name
Registration Test

Transaction Number
12182213

Attempt
1

Service Fees

AED 170 Collected on 19/07/2020

Received by

Raul Canceran Galang

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا

إقتناء التأمين للسيارة لسنة 2021 لسنة 1995

