

Queue Number

2685095

Transaction Date

27 Aug 2026, 14:05:15

Site Name

840 - Emirates Auctions

Transaction Number

49624761 (CC10021) (CC10011)



Vehicle Details

Chassis Number

SCBEA5ZA0E*****

Specification

GCC Specification

Make

Bentley

Model

Flying Spur

Model Year

2014

Color

White

Mileage

131097 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

12

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT LEFT SIDE,REAR RIGHT REPAINTED PORTION REPAIRED,FRONT RIGHT SIDE PORTION REPAIRED REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REFITTED , REAR RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER NEATH COVERED,PORTION PORTION DAMAGED,MISSING	الارضية
01.F Bumper	MINOR MISALIGN,GRILL PORTION DAMAGED	دعامية
01.G Bonnet	STAY SHOCK NOT WORKING	غطاء المحرك
01.H Trunk	FIBER PAINT NOT CHECK	صندوق
01.I Door Handle & Lock	FRONT RIGHT SIDE DOOR AUTO CLOSE NOT WORKING	مقابض الأبواب والأقفال

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,MUDDY,CHECKED VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	NEED TO REMOVE BOTH SIDE FENDER INNER COVER FOR PROPER INSPECTION	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS REFITTED,MINOR OIL LEAK,PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	ADJUSTMENT SWITCH PORTION DAMAGED WORN OUT,DRIVER SEAT BACK FOLDING TABLE MIRROR NOT CLOSE LOCK DAMAGED	حالة المقاعد
---------------------	---	--------------

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED,MINOR OIL LEAK,PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	GETTING CRACKED	الاضاءة الرئيسية
08 Interior Condition		الحالة الداخليه
08.A Mirror	CENTER VIEW MIRROR MINOR LOOSE	المرايا
08.B AC Condition	OK	المكيف
08.C Roof Light	FRONT PANEL LOOSE,REAR DAMAGED	أنارة السقف
08.D Power Window Switch And Glass	CURTAIN PORTION DAMAGED LOOSE NOT WORKING PROPERLY,LEFT SIDE COVER MISALIGN	مفتاح النافذه و الزجاج
08.E Sun Visor	LEFT SIDE MIRROR LIGHT NOT WORKING	حاجب الشمس
08.F Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم
08.G Gear Shifting Lever	KNOB GETTING WORN OUT	ذراع نقل السرعات
08.H Engine Start Button	WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae