



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	09 May 2022, 17:04:51
Transaction Number	80769975 (CC10006)	Queue Number	312309



Chassis Number	5TFUY5F17GX502495
Engine Number	
Vehicle Class	Heavy
Manufacturer	Toyota
Model	Tundra
Model Year	2016
Color	Silver
Mileage	112391 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY TOTALLY REPAINTED EXCEPT ROOF, PORTION REPAIRED DENTS SCRATCHES ON BODY	الصبغ
01.B Bumper	FRONT BUMPER FRAME , BULK HEAD REFITTED , BOLTES MISSING	دعامية
01.C Fenders	RIGHT SIDE FAIR WALL CRACKED	مدكار
01.D Bonnet	REPAINTED REFITTED	غطاء المحرك
01.E Doors	REPAINTED , REFITTED	أبواب
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
03 Interior Condition		الحالة الداخليه
03.A Air Bag	BOTH SIDE AIR BAG DAMAGED	وسائد هوائية
03.B AC Condition	OK	المكيف
04 Engine Condition		المحرك
04.A Visual Engine Condition	SIGN OF MINOR OIL LEAK , REFITTED	حالة المحرك النظري
04.B Smoke	WHITE SMOKE	دخان

DEFECT	REMARKS	
05 Suspension System		ممتص الصدمات
05.A Arms	LOWER ARM BUSHES MINOR CRACKED	ازرع
05.B Ball Joint	BOOT CUT	مفصل كروي
06 Steering Condition		المقود
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
07 Chassis Condition		الشاصي
07.A Chassis	OK	الشاسيه
08 Transmission Condition		الجير
08.A Road Test	NOT CHECKED	فحص علي الطريق
08.B Visual Gear Box Condition	SIGN OF MINOR OIL LEAK , REFITTED	حالة الجير النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.