



Test Certificate

Site Number	: 756-SHJ AUTO VILLAGE	Plate Code	:	
Transaction Number	: 20092917	Plate Category	:	
Transaction Date	: 30 JUN 2020 13:50:18	Plate Number	:	
Queue Number	: 191056	Import Doc. Ref.	:	02523 EA
Chassis Number	: 2T1BURHE6JC002523	Manufacturer/Model	:	TOYOTA/COROLLA
Engine Number	:	Model Year	:	2018
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	:	BLACK
Service / Indicator	: DSC AUCTION	Mileage	:	22823

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
17 Shock Absorbers Test		فحص مخمد الصدمات
17.01 - Shock Absorber Test	Passed	فحص مخمد الصدمات
VISUAL TEST:		
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		ALL TYRES 2017 CRACKED.
05 Body		الهيكل
05.05 - Bumpers		الدعامية
		FRONT BUMPER,FENDERS & BONNET REFITTED.
05.12 - Side Safety Frame		الواقيات الجانبية
		FRONT BULK HEAD REPAIRED.
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.06 - Chassis Ok	OK	الشاصي جيد
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط
تسجيل غير مسؤولة عن العيوب الخفية