



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	12 Oct 2021, 17:11:31
Transaction Number	94904684 (CC10006)	Queue Number	312309



Chassis Number	2FMDK4KC9BBA73942
Engine Number	
Vehicle Class	Car
Manufacturer	Ford
Model	Edge
Model Year	2011
Color	Red
Mileage	0 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED	الصبغ
01.B Fenders	FRONT LEFT FENDER REPAINTED&RIGHT FENDER REFITIED	مدكار
01.C Bonnet	REPAINTED,REFITIED	غطاء المحرك
01.D Doors	FRONT RIGHT DOOR REPAINRED	أبواب
01.E Roof	SUNROOF NOT WORKING	السقف
01.F Other	ODOMETER READING 138725	اخرى
02 Interior Condition		الاجزاء الداخلية
02.A AC Condition	AC NOT COOLING	المكيف
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2011 CRACKED & EXPIRED	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2011 CRACKED & EXPIRED	الاطار الخلفي
04 Chassis Condition		الشاسي
04.A Chassis	OK	الشاسيه
05 Engine Condition		المحرك
05.A Other	OK	اخرى

DEFECT	REMARKS	
06 Transmission Condition		الجير
06.A Gear Box	OK	الجير
07 Exhaust System		نظام العادم
07.A Other	GETTING MINOR RUSTY	اخرى
08 Wipers and Arms		المساحات
08.A Other	WORN OUT	اخرى
09 Seats Condition		المقاعد
09.A Other	OK	اخرى
10 Lights		الاضاءة
10.A Head Light	OK	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.