

Queue Number 2735721

Transaction Date 11 Sep 2026, 16:38:22

Site Name
840 - Emirates AuctionsTransaction Number
84504170 (CC10013) (CC10013)

Vehicle Details

Chassis Number	SJAAB1ZV2H*****
Specification	GCC Specification
Make	Bentley
Model	Bentayga
Model Year	2017
Color	White
Mileage	157595 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY MINOR DENT SCRATCHES / PORTION GETTING FADED	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR FULLY COVERED PORTION DENTS, MUDDY	الارضية
01.D Bumper	MINOR SCRATCHES / GRILL PORTION DAMAGED	دعامية
01.E Other	ELECTRIC ISSUE	اخرى
01.F Trunk	AUTO NOT WORKING PROPERLY	صندوق
01.G Fuel Tank	OUTER COVER MISALIGN	خزان الوقود

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH & REMOVE INNER FENDER UNDER ENGINE FLOOR COVER FOR RECHECK	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	SHAKING , MISFIRING , PARTS GETTING RUSTY MUDDY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Exhaust System

نظام العادم

04.A Other	DENT	اخرى
------------	------	------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2021 EXPIRED CRACKED	الاطار الامامي
06.B Rear Tyre	2021 EXPIRED CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES / FRONT LEFT NUT MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنايير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	MINOR LEAK	ممتص الصدمات
09.B Arms	LOWER ARM BUSHES DRY CRACK	ازرع
09.C Other	SUSPENSION PARTS REFITTED	اخرى
09.D Hydraulic System	NOT WORKING PROPERLY	النظام الهيدروليكي
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS MINOR DIRTY GETTING RUSTY	اخرى
10.B Mirror	LEFT SIDE VIEW MIRROR COVER PORTION DAMAGED / BRACKET LOOSE	المرآيا
10.C AC Condition	BLOWER COOLING FAN NOT WORKING / REAR OK	المكيف
10.D Dash Board	GETTING FADED PORTION WORN OUT	لوحة القيادة
10.E Roof Ceiling	GRAB HANDLE WORN OUT	بطانه السقف
10.F Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم
10.G Sunroof	NOT WORKING PROPERLY	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on

للسكاوي والمقترحات يمكنك التواصل معنا عبر

