

Queue Number 2874492

Transaction Date 16 Oct 2026, 12:27:34

Site Name
840 - Emirates AuctionsTransaction Number
81038963 (CC10013) (CC10011)

Vehicle Details

Chassis Number	JTMHU09J2F*****
Specification	GCC Specification
Make	Toyota
Model	Land Cruiser
Model Year	2015
Color	White
Mileage	125201 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,EXCEPT ROOF,DENTS SCRATCHES,PORTION FADED GETTING RUSTY(BODY SHAPE CHANGE OLD TO NEW MODEL)	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOORBODY MOUNT RUBBER DRY CRACK	الارضية
01.E Bumper	MISALIGN,PORTION DAMAGED MODIFIED	دعامية
01.F Bonnet	REFITTED,STAY SHOCK NOT WORKING	غطاء المحرك
01.G Pillars	RIGHT SIDEA/C/PILLAR OUTER PANEL REPAINTED PORTION REPAIRED	القوائم
01.H Trunk	TAILGATE REFITTED,INNER COVER PORTION DAMAGED LOOSE,CHROME PANEL PORTION CRACKED	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME DIRTY MUDDY GETTING RUSTY PORTION DENT	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Other	ELECTRIC WIRE WORN OUT UNSAFE / UPPER COVER PORTION DAMAGED	اخرى
03.B Engine Visual Condition	OIL LEAK , OPEN REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	REAR SEATS BACK COVER PORTION LOOSE,LEFT SIDE FOLDING NOT WORKING PROPERLY	حالة المقاعد
---------------------	--	--------------

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Modification	EXHAUST SYSTEM MODIFIED	تعديلات
05.B Catalytic Converter	MISSING	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	REFITTED , MINOR OIL LEAK , PARTS GETTING RUSTY	الحالة النظرية للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
08 Lights		الاضاءة
08.A Tail Light	FADED,RIGHT SIDE PORTION DAMAGED	الضوء الخلفي
08.B Fog light	FADED	كشف الضباب
09 Brake Condition		الفرامل
09.A Hand Brake	DUST COVER LOOSE	فرامل اليد
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	LEAK	ممتص الصدمات
10.B Arms	ARM BUSHES DRY CRACK	ازرع
10.C Other	SUSPENSION PARTS MODIFIED	اخرى
10.D Ball Joint	BOOT CUT	مفصل كروي
10.E Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
11 Steering Condition		المقود
11.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
11.B Axle	BOOT CUT	اكسلات
12 Interior Condition		الحاله الداخليه
12.A Other	INTERIOR MODIFIED PARTS REFITTED GETTING RUSTY SIGN OF FLOODED	اخرى
12.B Mirror	BOTH SIDE ADJUSTMENT NOT WORKING PROPERLY,CENTER VIEW MIRROR PORTION FADED	المرايا
12.C AC Condition	FRONT LOW COOLING NOT WORKING PROPERLY,REAR NOT WORKING,GRILL PORTION DAMAGED	المكيف
12.D Roof Light	FRONT PANEL LOOSE	أنارة السقف
12.E Power Window Switch And Glass	FRONT RIGHT SIDE SWITCH PANEL LOOSE	مفتاح النافذه و الزجاج
12.F Audio	LCD PORTION CRACKED	صوتيات
12.G Roof Ceiling	PORTION LOOSE	بطانه السقف
12.H Sun Visor	BOTH SIDE LOOSE BRACKET DAMAGED	حاجب الشمس

Condition	Remarks	الحالة
12.I Door Panel	PORTION CRACKED,WORN OUT	لوحة بطانة الباب
12.J Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
12.K Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
13 Engine Cooling System		نظام تبريد المحرك
13.A Radiator Cooling Fan	SAFETY COVER PORTION DAMAGED	مروحة تبريد المبرد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae