CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2877718
Transaction Date	17 Oct 2026, 11:08:17
Site Name	840 - Emirates Auctions
Transaction Number	73657180 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JNRBS15Y09*******
Specification	GCC Specification
Make	Infiniti
Model	FX 50
Model Year	2009
Color	White
Mileage	186133 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDEREARIRED ,REPAINTED REFITTED . ,REAR BOTH SIDE REPAINTED PORTION REPAIRED ,REAR RIGHT SIDE SKIRT MISSING.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	REAR RIGHT SIDE REFITTED .	أبواب
01.D Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.G Bonnet	STAY SHOCK WEAK.	غطاء المحرك
01.H Trunk	NOT OPEN .	صندوق
01.I Sign of back accident	BACK PANEL ,QUARTER PANEL ,SPARE WHEEL HOUSING REPAIRED,DENT .	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	REAR BOTH SIDE CHASSIS EXTENSION REPAIRED DENT ,FRONT CHASSIS COVERED OILY MUDDY.	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	WHITE SMOKE.	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY,COOLANT LEAKING ,	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE PORTION CUT .	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACKED WORN OUT .	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES .,	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED .	الاضاءة الرئيسية
07.B Warning Light	EXTRA WARNING LIGHT ,MESSAGE ON IN CLUSTER.	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY.	دواسة الفرامل
08.B Disc&Drum	RUSTY .	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	BOOT CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS RUSTY,SIGN OF FLOODED.	اخري
11.B AC Condition	NOT COOLING.	المكيف
11.C Power Window Switch And Glass	MAIN SWITCH LOOSE.	مفتاح النافذه و الزجاج
11.D Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.E Steering Wheel and control buttons	WORN OUT,	عجلة القيادة وازرار التحكم
11.F Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**