



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	16 Aug 2022, 11:44:04
Transaction Number	13914308 (CC10008)	Queue Number	312309



Chassis Number	RKLBV42EXC4437076
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Corolla
Model Year	2012
Color	Silver
Mileage	120233 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
01.B Dash Board	CENTER FRAME DAMAGED	لوحة القيادة
01.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2019/2020	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2019/2020	الاطار الخلفي
03 Engine Condition		المحرك
03.A Visual Engine Condition	MINOR OIL LEAK & REFITTED	حالة المحرك النظري
03.B Mount	MOUNT RUBBER CRACKED	كرسي
03.C Smoke	BLACK SMOKE	دخان
04 Steering Condition		المقود
04.A Tie Rod End	BOOT CUT	مؤخرة الروداد
05 Suspension System		ممتص الصدمات
05.A Shock Absorber	REAR SHOCK LEAK	ممتص الصدمات

DEFECT	REMARKS	
05.B Arms	LOWER ARM BUSHES CRACKED	ازرع
05.C Ball Joint	BOOT CUT	مفصل كروي
06 Transmission Condition		الجير
06.A Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
06.B Road Test	NOT CHECK	فحص علي الطريق
06.C Visual Gear Box Condition	MINOR OIL LEAK & REFITTED, JERKING	حالة الجير النظرى
07 Chassis Condition		الشاسي
07.A Chassis	REAR BOTH SIDE CHASSIS EXTENSION END REPAIRED	الشاسيه
08 Body		جسم المركبة
08.A Paint	BODY REPAINTED , PORTION REPAIRED MINOR DENTS SCRATCHES , PORTION FADED	الصبغ
08.B Sign of back accident		وجود مؤشر لحادث في الخلف
08.C Floor	RIGHT SIDE FLOOR JOINT MINOR DETACHED	الارضيه
09 Brake Condition		الفرامل
09.A Brake Pedal	SPONGY & WEAK	دواسة الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Possession Certificate :	66753591
Chassis No :	RKLBV42EXC4437076
Vehicle Make :	TOYOTA
Vehicle Model :	COROLLA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Silver
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	120234 Kms. x
Previous Odometer Reading :	701520 Kms.
Origin : Taiwan	Model Year : 2012
Gear Type : Automatic	Engine Size : 1600 CC
Engine No : 1ZR 0865100	Horse Power : 64
Axles No : 2	Cylinders : 4
No Of Doors : 4	No Of Seats : 5
G. V. W. : 1850 Kgs.	Empty Weight : 1350 Kgs.

Certificate Number :	5-TAS-2022-17428587		
Inspection Date :	17-08-2022		
Certificate Print Date :	17-08-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	13 min 3 sec		
Appointment Ref Number :	--		
Start Time :	13:11	End Time :	13:24
Lane :	02	Token No. :	154
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
17 %	3 %	6 %	0 %
Vehicle on Petrol HC Reading			
0 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Pedal BRAKE PEDAL SPONGY	Hard/spongy	Major
Paint REPAIR FADED PORTIONS	Others (Major)	Major
Dip beams(Low Beams) headlight RIGHT SIDE LOW BEAM	Defective	Major

Discrepancies	Old Value	New Value	Verified
Odometer Device Odometer Reading Change	Authorized	Replaced	

Inspection Remarks: FRONT BUMPER FRAME , BACK PANEL REPAIRED // UNDER NEATH OIL WETNESS // OLD KM - 701520



Odometer Record
Replace Events Date

17/08/2022

Payment Details

Inspection Performed by 30544 3104 3104	Payment Method Cash	Transaction Number 17428587	Service Fees AED 170 Collected on 17/08/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال



30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.