CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2976882
Transaction Date	12 Nov 2026, 15:45:32
Site Name	840 - Emirates Auctions
Transaction Number	70167213 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JS2ZC21S6A*******
Specification	GCC Specification
Make	Suzuki
Model	Swift
Model Year	2010
Color	Red
Mileage	397623 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED DENTS AND SCRATCHES PORTION RUSTY PORTION FADED	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION DENT MUDDY	الارضية
01.E Bumper	MISALIGN PORTION DAMAGED	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Pillars	BOTH SIDE C PILLARS ROCKER PANEL ROOF RAILS REPAIRED	القوائم
01.H Sign of front accident	FRONT BUMPER FRAME FENDER FRAME BULKHEAD RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL QUARTER PANEL COMPARTMENT FLOOR REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED DENT , GETTING RUSTY.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	NOT STARTING ALL SYSTEM NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE PORTION CUT	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SOD 2020 EXPIRED CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SODE 2020 EXPIR D CRACKED	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED ,ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	CRACKED	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	BUSHES CRACKED	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT	ربلة المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR CONDITION RUSTY SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECKED	المكيف
11.C Dash Board	PORTION LOOSE	لوحة القياده
11.D Sun Visor	LOOSE	حاجب الشمس
11.E Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	CAP MISSING	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae