

Queue Number

2891189

Transaction Date

20 Oct 2026, 16:20:16

Site Name

840 - Emirates Auctions

Transaction Number

82610576 (CC10009) (CC10012)



Vehicle Details

Chassis Number	JTFLU71JOD*****
Specification	GCC Specification
Make	Toyota
Model	Land Cruiser Pickup
Model Year	2013
Color	--
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED DENT SCRATCHES , PORTION RUSTY HOLE	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR COMPLETELY DIRTY MUDDY RUST PROOFED PORTION RUSTY HOLES	الارضية
01.D Bumper	PORTION DAMAGED	دعامية
01.E Pillars	PORTION RUSTY	القوائم
01.F Vehicle Color	WHITE	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	BOTH SIDE CHASSIS RUSTY DAMAGED CRACKED PORTION RUSTY BULGHED AND HOLES , COMPLETELY THICK RUST PROOFED	الشاسيه
02.B Chassis Number	RUSTY,NOT VISIBLE PROPERLY	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED OIL LEAK REFITTED /RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	EXTRA COVERS PORTION DAMAGED	حالة المقاعد
---------------------	------------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	NOT CHECKED OIL LEAK REFITTED/ RUSTY	الحالة النظرية للجير
--------------------------------	--------------------------------------	----------------------

Condition	Remarks	الحالة
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACK	الاطار الخلفي
06.C Rims Condition	HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , ALL LIGHT NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE CRACK , RIGHT SIDE DAMAGED	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Suspension Subframe	RUSTY HOLES	ممتص الصدمات ازرع اخرى مفصل كروي
08.B Shock Absorber	RUSTY	
08.C Arms	BUSHES CUT	
08.D Other	SUSPENSION RUSTY	
08.E Ball Joint	BOOT CUT	
09 Interior Condition		الحالة الداخليه
09.A Other	INNER PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
09.B AC Condition	NOT CHECK	المكيف
09.C Floor Matting	EXTRA COVER	فرش الأرضيه
09.D Dash Board	WORN OUT	لوحة القيادة
09.E Door Panel	WORN OUT	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae