



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	16 Jan 2022, 17:51:46
Transaction Number	56591604 (CC10006)	Queue Number	312309



Chassis Number	2G1FP22KXW2102566
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Camaro
Model Year	1998
Color	White
Mileage	78567 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	USA Imported

DEFECT	REMARKS	
01 Chassis Condition		الشاشي
01.A Chassis	OK	الشاسيه
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Gear Box	OK	الجير
03 Suspension System		ممتص الصدمات
03.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED, RUSTY	ازرع
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
05 Body		جسم المركبة
05.A Bonnet	REPAINTED	غطاء المحرك
05.B Rusty	UNDER BODY PARTS, SUSPENSION ,FLOOR, GETTING RUSTY	صدأ
05.C Fenders	FRONT BOTH SIDE BLASTIC (PAINT NOT CHECK) & REAR BOTH SIDE PORTION REPAIRED, REPAINTED	مدكار

DEFECT	REMARKS	
05.D Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
05.E Bumper	REPAINTED	دعامية
05.F Trunk	SHOCK WEAK	صندوق
06 Interior Condition		الحاله الداخليه
06.A Dash Board	COVER LOOSE	لوحة القيادة
06.B AC Condition	NOT COOLING	المكيف
06.C Door Panel	LOOSE	لوحة بطانة الباب
06.D Roof Ceiling	FRONT LOOSE	بطانه السقف
06.E Power Window Switch	LEFT SIDE LOCK DAMAGED	مفتاح النافذه
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
07.B Head Light	OK	الاضاءة الرئيسية
08 Engine Condition		المحرك
08.A Engine Condition	SIGN OF WET	حالة المحرك
08.B Mount	BUSHES CUT	كرسي
09 Seats Condition		المقاعد
09.A Seat Belt	BOTH SIDE NOT WORKING	حزام الأمان
09.B Seat Condition	REAR LOOSE	حالة المقاعد
10 Wipers and Arms		المساحات
10.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.