



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	14 Sep 2021, 16:30:04
Transaction Number	31715585 (CC10006)	Queue Number	312309



Chassis Number	JN8AY2NYXE9060186
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2014
Color	--
Mileage	238273

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	MINOR SCRATCHES ON BODY	الصبغ
01.B Rusty	UNDER BODY PARTS & CHASSIS GETTING RUSTY	صدأ
01.C Bumper	BUMPER FRAME MODIFIED	دعامية
02 Chassis Condition		الشاسي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Other	OK	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير
05.A Gear Box	OK	الجير
06 Wipers and Arms		المساحات
06.A Other	OK	اخرى
07 Lights		الاضاءة
07.A Head Light	OK	الاضاءة الرئيسية
07.B Other	OK	اخرى
08 Brake Condition		الفرامل

DEFECT	REMARKS	
08.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	GETTING RUSTY	ممتص الصدمات
09.B Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED, RUSTY	ازرع
09.C Suspension Subframe	REAR SUSPENTION SUB FRAME GETTING RUSTY	
10 Steering Condition		المقود
10.A Steering Boot	BOOT CUT & LEAKING	ربلة المقود
11 Interior Condition		الاجزاء الداخلية
11.A Other	OK	اخرى
11.B Mirror	OK	المرايا
11.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.