



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>24 Jan 2023, 13:35:14</b>
Transaction Number	<b>39936996 (CC10009)</b>	Queue Number	<b>662050</b>



Chassis Number	<b>1G1Y92D95K5800756</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Chevrolet</b>
Model	<b>Corvette</b>
Model Year	<b>2019</b>
Color	<b>Orange</b>
Mileage	<b>85902 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	OK	المكيف
01.B Floor Matting	PORTION LOOSE	فرش الأرضيه
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	BOTH SIDE 2019 WRON OUT	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Visual Gear Box Condition	VISUAL /OK	حالة الجير النظرى
03.B Road Test	AS DRIVE NOT CHECKED	فحص علي الطريق
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Visual Engine Condition	CHECKED VISIBLE AREA /OK UPPER COVER REFITTED	حالة المحرك النظرى
<b>05 Chassis Condition</b>		<b>الشاسي</b>
05.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
<b>06 Body</b>		<b>جسم المركبة</b>
06.A Paint	BODY FULLY FIBER PAINT CANNOT BE CHECKED	الصبغ

DEFECT	REMARKS	
06.B Floor	UNDER FLOOR FENDER CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY	الارضية

**07 Suspension System**

ممتص الصدمات

07.A Other	REAR SUSPENSION SUBFRAME REFITTED	اخرى
------------	-----------------------------------	------

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.