



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **25 Oct 2021, 18:10:32**
 Transaction Number **51159569 (CC10006)** Queue Number **312309**



Chassis Number **JN8FY1NY2DX000090**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Nissan**
 Model **Patrol**
 Model Year **2013**
 Color **Gold**
 Mileage **178274 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **6**
 Specification **GCC Specification**

DEFECT

REMARKS

01 Chassis Condition

الشاسي

01.A Chassis FRONT LEFT CHASSIS END REPAIRED&FRONT RIGHT
&REAR ARCH AREA MINOR BULGE

الشاسيه

02 Body

جسم المركبة

02.A Paint BODY PORTION REPAINTED,PORTION REPAIRED

الصبغ

02.B Fenders FRONT BOTH FENDER REPAINTED,PORTION
REPAIRED,RIGHT FRAME BEND&FENDER MISALIGN

مدكار

02.C Bumper REPAINTED

دعامية

02.D Doors FRONT BOTH DOOR REPAINTED,PORTION REPAIRED

أبواب

02.E Rusty UNDER BODY PART ,CHASSIS , GETTING MINOR RUSTY

صدأ

02.F Bonnet REPAINTED,PORTION REPAIRED,REFITIED

غطاء المحرك

02.G Other FRONT RADIATOR SUPPORT ,BUMPER FRAME ,BULK HEAD
REPAIRED

اخرى

02.H Floor REAR RIGHT INNER QUATER PANEL MINOR BEND

الارضية

03 Tires and Rims Condition

الاطارات

03.A Front Tyre BOTH SIDE 2019/2020 WORNOUT

الاطار الامامي

03.B Rear Tyre BOTH SIDE 2020 MINOR WORNOUT

الاطار الخلفي

03.C Spare Tire &Tools TOOLS MISSING

الاطار الاحتياطي و العدة

DEFECT

REMARKS

04 Transmission Condition

الجير

04.A DIFFERENTIAL

FRONT BOTH ROMINA OIL LEAK

الدفرنشل

04.B Road Test

NOT CHECK

فحص علي الطريق

04.C Gear Box

MINOR OIL LEAK,REFITIED

الجير

05 Engine Condition

المحرك

05.A Engine Condition

OPEN,REFITIED

حالة المحرك

06 Seats Condition

المقاعد

06.A Seat Belt

OK

حزام الأمان

06.B Seat Condition

REAR SEAT MISSING

حالة المقاعد

07 Wipers and Arms

المساحات

07.A Wiper Arm &Blade

WORN OUT

ازرع المساحات والشفرات

08 Interior Condition

الحالة الداخليه

08.A AC Condition

OK

المكيف

08.B Dash Board

DISPLAY SCREEN CRACKED

لوحة القيادة

08.C Audio

LEFT AUDIO BUTTON MISSING

صوتيات

08.D Odometer reading

178277 KM

قراءة عداد المسافات

08.E Floor Matting

REPLACED

فرش الأرضيه

09 Lights

الاضاءة

09.A Brake Light

CENTER BRAKE LIGHT INNER COVER MISSING&LIGHT NOT WORKING

نور الفرامل

09.B Fog light

LEFT NOT WORKING

كشف الضباب

10 Exhaust System

نظام العادم

10.A Modification

HEADERS

تعديلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate




✓ PASS

Plate Details :

Chassis No :	JN8FY1NY2DX000090
Vehicle Make :	NISSAN
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Golden
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	178284 Kms.
Origin :	Japan
Model Year :	2013
Gear Type :	--
Engine No :	TB48071942
Engine Size :	3500 CC
Horse Power :	--
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	7
G. V. W. :	1900 Kgs.
Empty Weight :	1600 Kgs.

Certificate Number :	5-TAS-2021-15317991
Inspection Date :	26-10-2021
Certificate Print Date :	26-10-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	16 min 26 sec
Appointment Ref Number :	--
Start Time :	13:25
End Time :	13:42
Lane :	01
Token No. :	144
Attempt :	1
Prints No :	1

Carbon footprint



Estimated Vehicle Consumption (Rate in 12 Months)

16207 KM	1668 L	2703 AED	4.0 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 3 %	Service brake imbalance on rear axle 5 %	Parking brake imbalance between LHS and RHS 1 %	Vehicle on Petrol CO Reading 0.16 %
Vehicle on Petrol HC Reading 0 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	4800	

Inspection Remarks:

FRONT LEFT SIDE CHASSIS END REPAIRED&FRONT RIGHT CHASSIS END MINOR BULGE/ FRONT BULKHEAD/FENDER&FRONT &REAR BUMPER &REAR RIGHT SIDE QUARTER PANEL REPAIRED/ MINOR FRONT RIGHT SIDE TIRE WORN&FRONT DIFFERENTIAL MINOR OIL LEAK

Payment Details

Inspection Performed by 62439	Payment Method Cash	Transaction Number 15317991	Service Fees AED 170 Collected on 26/10/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Hussain Basha Akeel

- ① This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
② Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفنى للمركبة. لا يهتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

