CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2990405
Transaction Date	14 Nov 2026, 13:04:00
Site Name	840 - Emirates Auctions
Transaction Number	10648989 (CC10013) (CC10011)



Vehicle Details

Chassis Number	MA3NC2B12S*******
Specification	GCC Specification
Make	Suzuki
Model	Ertiga
Model Year	2025
Color	White
Mileage	53186 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REPAIRED REPAINTED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION GETTING RUSTY	الصبغ
01.C Doors	FRONT BOTH SIDE REPAINTED PORTION REPAIRED LEFT SIDE REFITTED & REAR LEFT SIDE NOT OPEN	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR RUST PROOFED PORTION DENT SIGN OF ALIGN	الارضية
01.F Bumper	TOWING HOOK COVER,LEFT SIDE REFLECTOR MISSING	دعامية
01.G Roof	PORTION REPAIRED REPAINTED	السقف
01.H Bonnet	REPAIRED REPAINTED,REFITTED	غطاء المحرك
01.I Sign of front accident	FRONT BUMPER FRAME RADIATOR SUPPORT BULK INNER FENDER FRAME APRON AREA REPAIRED ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED GETTING RUSTY	الشاسيه
03 Engine Condition		**المحرك**
03.A Other	INNER ELECTRIC WIREING WORN OUT UNSAFE	اخري
03.B Engine Visual Condition	REFITTED , OIL PAN HOUSING BOLT DAMAGED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**

Condition	Remarks	الحالة
04.A Seat Condition	REAR SEATS MISSING CABIN MODIFIED	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	MANIFOLD COVER MISSING	اخري
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	MINOR JERKING , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي
07.B Rear Tyre	LEFT SIDE 2024 CRACK,RIGHT 2025	الاطار الخلفي
07.C Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
08.B Brake Light	NOT WORKING	نور الفرامل
09 Brake Condition		الفرامل
09.A Disc&Drum	GETTING RUSTY	دسك وطنابير الفرامل
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY	اخري
10.B AC Condition	OK,GRILL PORTION DAMAGED	المكيف
10.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11 Battery Condition		حالة البطارية
11.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae