CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2941680
Transaction Date	06 Nov 2026, 10:14:53
Site Name	840 - Emirates Auctions
Transaction Number	82280944 (CC10008) (CC10011)



Vehicle Details

Chassis Number	1C4RJFJTXF*******
Specification	GCC Specification
Make	Jeep
Model	Grand Cherokee
Model Year	2015
Color	White
Mileage	207000 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REFITTED	مدكار
01.B Paint	MINOR DENT SCRATCHES ON BODY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR PORTION GETTING RUSTY	الارضية
01.E Bumper	FRONT MODIFIED & MISALIGN,PORTION MODIFIED HOLES	دعامية
01.F Bonnet	REFITTED,LOGO MODIFIED	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS GETTING RUSTY ,DELAY START	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Belt	FRONT BOTH SIDE NOT WORKING PROPERLY	حزام الأمان
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS GETTING RUSTY ,MINOR JERKING	الحالة النظريه للجير
05.B DIFFERENTIAL	REAR MOUNT BUSHES CRACK	الدفرنشل
05.C Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 CRACKED EXPIRED	الاطار الخلفي
07 Lights		الاضاءة
07.A Tail Light	HAVE STICKER	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Hand Brake	PEDAL RUBBER MISSING	فرامل اليد
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	MODIFIED	ممتص الصدمات
09.B Hydraulic System	NOT WORKING	النظام الهيدروليكي
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,CENTER CUP HOLDER PANEL PORTION WORN OUT,PART REFITTED	اخري
10.B AC Condition	NO COOLING,GRILL CASE MODIFIED	المكيف
10.C Power Window Switch And Glass	FRONT BOTH SIDE SWITCH LOOSE	مفتاح النافذه و الزجاج
10.D Audio	LCD MODIFIED	صوتيات
10.E Dash Board	PORTION DAMAGED,LEATHER PORTION LOOSE	لوحة القياده
10.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.H Engine Start Button	GETTING WORN OUT,REMOTE DAMAGED	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae