



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	06 Oct 2021, 17:49:12
Transaction Number	94278330 (CC10006)	Queue Number	312309



Chassis Number	JTHBE5D23E5011781
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	IS 350
Model Year	2014
Color	Silver
Mileage	98712 N/A

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	REPAIRED , REPAINTED & REAR TRUNK NOT OPEN	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR DENT & PORTION COVERD	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Roof	ROOF, ROOF RAIL REPAIRED (FOR RECHECK PROPERLY NEED TO REMOVE INNER COVER)	السقف
01.H Pillars	ALL REPAIRED (FOR RECHECK PROPERLY NEED TO REMOVE PIILARS, ROCKER PANEL & BEEDING COVER)	القوائم
01.I Other	FRONT FENDER FRAME, WHEEL HOUSING REPAIRED	اخرى
02 Chassis Condition		الشاسي
02.A Chassis	FRONT RIGHT SIDE REPAIRED	الشاسيه
02.B Other	VIN NUMBER AREA DENT	اخرى
03 Engine Condition		المحرك
03.A Other	OK	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Gear Box	OK	الجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	WORN OUT	اخرى
08 Brake Condition		الفرامل
08.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
09 Lights		الاضاءة
09.A Head Light	OK	الاضاءة الرئيسية
10 Interior Condition		الاجزاء الداخلية
10.A Other	PILLAR COVER LOSE, DASH BORAD CRACKED	اخرى
10.B Mirror	OK	المرايا
10.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate




✓ PASS

Plate Details :	N 34382 Dubai Private		
Chassis No :	JTHBESD23E5011781		
Vehicle Make :	LEXUS		
Vehicle Model :	IS 350		
Vehicle Class :	Light Vehicle		
Body Type :	SALOON		
Fuel :	Benzene		
Color :	Silver		
Drive Direction :	Left Hand Side		
Dimensions : (H x W x L) :	-- x -- x --		
Current Odometer :	98715 Kms.		
Origin :	Japan	Model Year :	2014
Gear Type :	Automatic	Engine Size :	3500 CC
Engine No. :	2GR8850412	Horse Power :	310
Axles No. :	2	Cylinders :	6
No Of Doors :	4	No Of Seats :	5
G. V. W. :	2000 Kgs.		
		Empty Weight :	1250 Kgs.

Certificate Number :	1-TAS-2021-15201243		
Inspection Date :	10-10-2021		
Certificate Print Date :	10-10-2021		
Services :	Renewal Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	17 min 48 sec		
Appointment Ref Number :	--		
Start Time :	11:54	End Time :	12:12
Lane :	01	Token No. :	144
Attempt :	1	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

10776 KM	1109 L	1797 AED	2.7 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 8 %	Service brake imbalance on rear axle 2 %	Parking brake imbalance between LHS and RHS 1 %	Vehicle on Petrol CO Reading 0.03 %
Vehicle on Petrol HC Reading 41 PPM VOL			

Inspection Remarks:

RIGHT SIDE A,B,C PILLAR,LEFT SIDE DOOR POST & BOTH SIDE ROOF RAIL FRONT RIGHT SIDE FENDER FRAME,BULK HEAD,RADIATOR SUPPORT REPAIRED

Payment Details

Inspection Performed by 62439	Payment Method Cash	Transaction Number 15201243	Service Fees AED 170 Collected on 10/10/2021
Parking Slot No --	Service Name Renewal Test	Attempt 1	Received by Hussain Basha Akeel

① This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

② Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

