

Queue Number 2844368

Transaction Date 07 Oct 2026, 14:14:28

Site Name
840 - Emirates AuctionsTransaction Number
25121552 (CC10013) (CC10011)

Vehicle Details

Chassis Number	WBAEA51078*****
Specification	GCC Specification
Make	BMW
Model	650 i
Model Year	2008
Color	Black
Mileage	195736 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE FIBER PAINT NOT CHECK PORTION CRACKED,REAR RIGHT REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED	الصبغ
01.C Doors	RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED / COVER PORTION DAMAGED MINOR DENT	الارضية
01.F Bumper	MISALIGN PORTION CRACKED,REFLECTOR PORTION CRACK	دعامية
01.G Bonnet	LOGO MISSING	غطاء المحرك
01.H Trunk	FIBER PAINT NOT CHECK,STAY SHOCK NOT WORKING	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED MUDDY DIRTY OILY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Smoke	MINOR WHITE	دخان
03.B Engine Visual Condition	OIL LEAK DRIPPING , REFITTED , PARTS GETTING RUSTY , ABNORMAL NOSIY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED WORN OUT,BACK COVER PORTION LOOSE	حالة المقاعد
---------------------	---	--------------

05 Exhaust System

نظام العادم

Condition	Remarks	الحالة
05.A Other	CUT REWELDED	اخرى
05.B Catalytic Converter	MISSING	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	RFEITTED , PARTS GETTING RUSTY	الحالة النظره للجير
06.B Road Test	NOT CHECKED	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
08.B Tail Light	PORTION CRACKED	الضوء الخلفي
08.C Indicator & Hazard light	FRONT BOTH SIDE INDICATOR LIGHT LOOSE	الاشارات
08.D Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	ARM BUSHES CRACK	ازرع
09.C Ball Joint	BOOT CUT	مفصل كروي
10 Steering Condition		المقود
10.A Steering Oil	OIL LEAK	زيت المقود
10.B Steering Boot	BOOT CUT	ربلة المقود
10.C Tie Rod End	BOOT CUT	مؤخرة الروداد
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX COVER PORTION WORN OUT / INTERIOR PARTS GETTING RUSTY	اخرى
11.B Mirror	BOTH SIDE AUTO FOLDING,RIGHT SIDE ADJUSTMENT NOT WORKING GETTING FADED,LEFT SIDE MINOR LOOSE	المرايا
11.C AC Condition	OK	المكيف
11.D Roof Light	NOT WORKING PROPERLY,COVER PART MISSING	أنارة السقف
11.E Power Window Switch And Glass	RIGHT SIDE NOT WORKING,BOTH SIDE SWITCH PANEL LOOSE	مفتاح النافذه و الزجاج
11.F Dash Board	PORTION LOOSE,LEATHER REFITTED	لوحة القيادة
11.G Roof Ceiling	LOOSE	بطانه السقف
11.H Odometer reading	CLUSTER PANEL DISPLAY PORTION FADED	قراءة عداد المسافات
11.I Door Panel	PORTION WORN OUT LOOSE	لوحة بطانة الباب
11.J Steering Wheel and control buttons	WORN OUT,INNER COVER LOOSE PORTION DAMAGED	عجلة القيادة وازرار التحكم
11.K Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
11.L Engine Start Button	FADED,REMOTE PORTION DAMAGED	زر تشغيل المحرك

Condition	Remarks	الحالة
12 Engine Cooling System		نظام تبريد المحرك
12.A Coolant tank	WATER LEVEL LOW	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae