

TEST CERTIFICATE

6G1EK6B39L183204

المحرك

Site Number
Transaction Number

05 Engine Condition

840-Emirates Auctions

49163265 (CC10006)

Transaction Date 14 Oct 2021, 09:44:46

Queue Number 312309

Chassis Number

Chassis Mailibei

Engine Number

Vehicle Class

Manufacturer

turer Chevrolet

Model Year

Color

Mileage

Model

White 0

Car

Lumina 2009

REMARKS DEFECT 01 Body جسم المركبة 01.A Paint **BODY PORTION REPAIRED & REPAINTED** الصبغ 01.B Fenders FRONT FENDER REPAIRED, REPAINTED مدكار 01.C Doors RIGHT DOOR &FRONT LEFT DOOR أبواب REPAIRED, REPAINTED&REAR POWER WINDOW NOT WORKING 01.D Floor BACK PANEL REPAIRED &UNDER BODY RUST PROOFED الارضية 01.E Bonnet **BONNET STAND WEAK** غطاء المحرك 01.F Other FROTN IINNER DOOR HANDE BROKEN &INNER DOOR PADS اخري LEATHER DAMAGED 01.G Roof SUNROOF NOT WORKING &ROOF CEILING السقف LOSE&SUNVISOR BRACKET BROKEN REPAINTED 01.H Bumper دعامية **02 Wipers and Arms** المساحات 02.A Other **WORN OUT** اخری **03 Interior Condition** الاجزاء الداخلية 03.A AC Condition OK المكيف **04 Lights** الاضاءة 04.A Head Light HEAD LIGHT LENS FADED &HEAD LIGHT BRACKET BROKEN الاضاءة الرئيسية

DEFECT	REMARKS	
05.A Other	OK	اخري
06 Transmission Condition		الجير
06.A Gear Box	OIL LEAK,REFITID	الجير
06.B Gear Box Mount	TRANSMISSION SHIFT COVER BROKEN	كرسي الجير
06.C Propeller Shaft	GEAR SHITING JARK&PROPELLER SHAFT FLANGE RUUBER CRACKED	ناقل الحركة
07 Suspension System		ممتص الصدمات
07.A Suspension Subframe	FRONT SUSPENSION SUB FRAME MINOR DENT	
08 Chassis Condition		الشاصي
08.A Chassis	OK	الشاسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.