CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934061
Transaction Date	03 Nov 2026, 12:50:39
Site Name	840 - Emirates Auctions
Transaction Number	34904030 (CC10010) (CC10010)



Vehicle Details

Chassis Number	1N4AL3A99E*******
Specification	GCC Specification
Make	Nissan
Model	Altima
Model Year	2014
Color	Black
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	BOTH SIDE REPAINTED REFITTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.F Bonnet	REFITTED, REPAINTED.	غطاء المحرك
01.G Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.H Vehicle Color	WHITE.	لون المركبة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS SUSPECT TO REPAIREED	الشاسيه
02.B Other	NEED TO REMOVE FENDER COVER UNDER COVER FOR INSPECTION .	اخري
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 CRACKED	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CRACKED.	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
10.B AC Condition	NOT CHECKED.	المكيف
10.C Dash Board	PARTS MISSING	لوحة القياده
10.D Odometer reading	NOT CHECKED .	قراءة عداد المسافات
10.E Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae