

Queue Number

2852295

Transaction Date

09 Oct 2026, 16:35:11

Site Name

840 - Emirates Auctions

Transaction Number

51047997 (CC10013) (CC10011)



Vehicle Details

Chassis Number	WP1ZZZ92ZG*****
Specification	GCC Specification
Make	Porsche
Model	Cayenne S
Model Year	2016
Color	Grey
Mileage	143060 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE SMART REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED,REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED DIRTY	الارضية
01.F Bumper	MISALIGN,MINOR DENT SCRATCHES	دعامية
01.G Bonnet	SHOCK WEAK	غطاء المحرك
01.H Door Handle &Lock	REAR LEFT SIDE DOOR OUTER HANDLE SENSOR BUTTON RUBBER MISSING	مقابض الأبواب والأقفال

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED MUDDY DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	MINOR OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	COVER PORTION DAMAGED CRACKED WORN OUT	حالة المقاعد
---------------------	--	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	--------------------------------	----------------------

Condition	Remarks	الحالة
05.B DIFFERENTIAL	REAR MOUNT RUBBER CRACK	الدفرنشل
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Other	BOTTLE PORTION DAMAGED	اخرى
08 Lights		الاضاءة
08.A Head Light	LENS GETTING FADED,LEFT SIDE WASHER COVER LOOSE	الاضاءة الرئيسية
09 Suspension System		ممتص الصدمات
09.A Suspension Subframe	MOUNT RUBBER DRY CRACK	ازرع اخرى
09.B Arms	ARM BUSHES DRY CRACK	
09.C Other	SUSPENSION PARTS REFITTED	
10 Interior Condition		الحالة الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B Mirror	CENTER VIEW MIRROR BACK COVER LOOSE	المرايا
10.C AC Condition	OK	المكيف
10.D Power Window Switch And Glass	FRONT LEFT SIDE SWITCH DAMAGED,RIGHT SIDE NOT WORKING	مفتاح النافذه و الزجاج
10.E Dash Board	LEATHER PORTION LOOSE WORN OUT	لوحة القيادة
10.F Roof Ceiling	LOOSE	بطانه السقف
10.G Door Panel	PORTION WORN OUT LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.I Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae