CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2979001
Transaction Date	12 Nov 2026, 16:28:34
Site Name	840 - Emirates Auctions
Transaction Number	43498756 (CC10009) (CC10019)



Vehicle Details

Chassis Number	ZARCABC43M*******
Specification	GCC Specification
Make	Alfa Romeo
Model	Giulietta
Model Year	2021
Color	Grey
Mileage	102221 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REPAINTED,PORTION REPAIRED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES,	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED,	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Sign of front accident	FRONT BUMPER BULK HEAD ASSMEBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA OK	الشاسيه
02.B Other	REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	اخري
03 Engine Condition		المحرك
03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	OIL LEAK OPEN REFITTED SHAKING NOISY GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	MINOROIL LEAK OPEN REFITED, DELAY SHIFTTING	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2022 CRACKED	الاطار الخلفي
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
06.B Fog light	NOT WORKING	كشاف الضباب
07 Brake Condition		الفرامل
07.A Brake Pedal	WEAK	دواسة الفرامل
08 Suspension System		ممتص الصدمات
08.A Other	SUSPENSION REFITTED	اخري
09 Steering Condition		المقود
09.A Steering Oil	OIL WET	زيت المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INETRIOR PARTS GETTING RUSTY, WATER FLOODED	اخري
10.B AC Condition	OK	المكيف
10.C Power Window Switch And Glass	FRONT LEFT SIDE SWITCH BUTTON CRACKED	مفتاح النافذه و الزجاج
10.D Dash Board	PORTION BULGED	لوحة القياده
10.E Sun Visor	RIGHT SIDE PORTION LOOSE	حاجب الشمس
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae