

Queue Number 2822634

Transaction Date 01 Oct 2026, 14:24:37

Site Name
840 - Emirates AuctionsTransaction Number
70106155 (CC10010) (CC10010)

Vehicle Details

Chassis Number	VF30U5FV9B*****
Specification	GCC Specification
Make	Peugeot
Model	3008
Model Year	2011
Color	Black
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED.	مذكرار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	LEFT SIDE REPAINTED PORTION REPAIRED ,FRONT LEFT DOOR MISALIGNED.	أبواب
01.D Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	MISALIGNED SCRATCHES .	دعامية
01.G Trunk	REPAIRED REPAINTED ,NOT OPEN ..	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,OILY MUDDY , CHECKED ONLY VISIBLE AREA/OK,	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظرية للجير
--------------------------------	--	----------------------

04.B Road Test	NOT CHECKED .	فحص علي الطريق
----------------	---------------	----------------

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021 EXPIRED CRACKED.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024/2021 EXPIRED CRACKED.	الاطار الخلفي
05.C Rims Condition	MINOR DENTS SCRATCHES.	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED ,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK,	ممتص الصدمات
08.B Arms	BUSHES CRACKED .	ازرع
09 Steering Condition		المقود
09.A Tie Rod End	BALL JOINT BOOT CRACKED.	مؤخرة الرودادات
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR CONDITION RUSTY ,SIGN OF FLOODED.	اخرى
10.B Dash Board	PORTION CRACKED ,GLOVE BOX LOOSE.	لوحة القيادة
10.C Roof Ceiling	PORTION LOOSE.	بطانة السقف
10.D Odometer reading	NOT CHECKED.	قراءة عداد المسافات
10.E Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae