

Queue Number

2878360

Transaction Date

19 Oct 2026, 12:12:18

Site Name

840 - Emirates Auctions

Transaction Number

81784297 (CC10008) (CC10025)



Vehicle Details

Chassis Number	JE3AB36A7H*****
Specification	GCC Specification
Make	Mitsubishi
Model	Lancer
Model Year	2017
Color	Black
Mileage	162016 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED , FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR BOTH SIDE & FRONT RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN , DAMAGED LOOSE, HOOK COVER MISSING	دعامية
01.F Roof	REPAINTED PORTION REPAIRED	السقف
01.G Bonnet	REPAINTED	غطاء المحرك
01.H Pillars	LEFT SIDE C/ PILLAR OUTER PANEL REPAIRED	القوائم
01.I Trunk	REPAINTED PORTION REPAIRED , REFITTED	صندوق
01.J Sign of side accident		وجود مؤشر لحادث في الجانب
01.K Sign of back accident	BUMPER FRAME BEND	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis Extension	REAR BOTH SIDE EXTENSION END ALIGN REPAIRED	تمديدات الشاسي
02.B Chassis	CHASSIS COVERED CHECKED VISIBLE AREA / OK	الشاسية

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET	الحالة النظرية للمحرك
------------------------------	---------	-----------------------

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	MINOR OIL LEAK	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 GETTING WORN OUT	الاطار الامامي
05.B Rear Tyre	LEFT SIDE 2023 , RIGHT SIDE 2021 EXPIRED CRACK	الاطار الخلفي
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
06.B Brake Light	NOT WORKING	نور الفرامل
06.C Fog light	LEFT SIDE NOT WORKING	كشف الضباب
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك و طنايبير الفرامل
08 Interior Condition		الحالة الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED ,INTERIOR DIRTY	اخرى
08.B Mirror	CENTER MIRROR PORTION LOOSE , GETTING FADED	المرآيا
08.C AC Condition	LOW COOLING , GRILL ADJUSTMENT MISSING	المكيف
08.D Sun Visor	LEFT SIDE MIRROR COVER MISSING	حاجب الشمس
08.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.F Gear Shifting Lever	KNOB WORN OUT , LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae