



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 May 2023, 15:16:40
Transaction Number	41216715 (CC10008)	Queue Number	726092



Chassis Number	KMHJT81BOBU174622
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	Tucson
Model Year	2011
Color	White
Mileage	384783 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Power Window Switch	FRONT RIGHT SIDE NOT WORKING	مفتاح النافذه
01.B Door Panel	FRONT LEFT SIDE PORTION DAMAGED	لوحة بطانة الباب
01.C Mirror	LEFT SIDE ADJUSTMENT NOT WORKING PROPERLY	المرايا
01.D AC Condition	LOW COOLING	المكيف
02 Transmission Condition		الجير
02.A Road Test	NOT CHECKED	فحص علي الطريق
02.B Visual Gear Box Condition	OIL WET ,REFITTED	حالة الجير النظري
03 Body		جسم المركبة
03.A Doors	LEFT SIDE BOTH REPAINTED,PORTION REPAIRED & REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	أبواب
03.B Fenders	REAR LEFT SIDE REPAINTED	مدكار
03.C Floor	BACK PANEL REPAIRED	الارضية
03.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
03.E Sign of back accident		وجود مؤشر لحادث في الخلف
03.F Trunk	PORTION REPAIRED,REPAINTED	صندوق

DEFECT	REMARKS	
03.G Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED,SPOT RUSTY	الصبغ
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2019,CRACKED	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2018,CRACKED	الاطار الخلفي
05 Seats Condition		المقاعد
05.A Seat Condition	EXTRA COVER	حالة المقاعد
06 Chassis Condition		الشاسي
06.A Chassis	REAR CHASSIS EXTENSION END REPIRED	الشاسيه
07 Suspension System		ممتص الصدمات
07.A Arms	LOWER ARM BUSHES CRACKED	ازرع
08 Engine Condition		المحرك
08.A Visual Engine Condition	OILWET ,REFITTED	حالة المحرك النظري
08.B Smoke	BLACK SMOKE	دخان
09 Lights		الاضاءة
09.A Head Light	LENS FADED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.