

Queue Number 2873752

Transaction Date 16 Oct 2026, 16:45:01

Site Name
840 - Emirates AuctionsTransaction Number
16688556 (CC10013) (CC10011)

Vehicle Details

Chassis Number	MMM156FB7H*****
Specification	GCC Specification
Make	Chevrolet
Model	Trailblazer
Model Year	2017
Color	Grey
Mileage	115408 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE,REAR LEFT REPAINTED PORTION REPAIRED & FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	FRONT RIGHT & REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK SIGN OF REFITTED	الارضية
01.F Bumper	MISALIGN,PORTION DENT SCRATCHES,LEFT SIDE REFLECTOR DAMAGED	دعامية

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME DIRTY OILY GETTING RUSTY	الشاسيه
02.B Chassis Number	VIN AREA GETTING RUSTY / CLEAN FOR CHECK	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--------------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2024 GETTING WORN OUT	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED,LEFT SIDE PORTION CRACK	الاضاءة الرئيسية
06.B Tail Light	RIGHT SIDE LENS MISSING	الضوء الخلفي
06.C Brake Light	RIGHT SIDE NOT WORKING	نور الفرامل
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES DRY CRACK	الزرع
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	OK,TEMPERATURE SWITCH PORTION DAMAGED	المكيف
08.C Power Window Switch And Glass	SWITCH PORTION FADED,REAR LEFT SIDE NOT WORKING PROPERLY	مفتاح النافذه و الزجاج
08.D Roof Ceiling	PORTION LOOSE	بطانه السقف
08.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.F Gear Shifting Lever	KNOB WORN OUT,SHIFT LOCK COVER MISSING	ذراع نقل السرعات
08.G Engine Start Button	REMOTE PORTION DAMAGED FIX BY TAPE	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae