CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2891533
Transaction Date	22 Oct 2026, 16:50:39
Site Name	840 - Emirates Auctions
Transaction Number	28347719 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JN1BF5ME8E*******
Specification	GCC Specification
Make	Nissan
Model	Juke
Model Year	2014
Color	Red
Mileage	253482 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REAR LEFT SIDE QUARTER PANEL REPAIRED REPAINTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Bumper	BUMPER MISALIGN ,SCRATCHES ,PORTION DAMAGED.	دعامية
01.F Windshield	FRONT CHANGED.	زجاج
01.G Bonnet	REPAIRED REPAINTED.	غطاء المحرك
01.H Sign of front accident	BULKHEAD REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	REAR LEFT SIDE CHASSIS EXTENSION END REPAIRED DENT . FRONT CHASSIS COVERED ,	الشاسيه
03 Engine Condition		**المحرك**
03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2022 EXPIRED CRACKED.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022 EXPIRED CRACKED. PUNCTURE.	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES,	حالة الجنوط
06 Lights		**الاضاءة**
06.A Head Light	LENS FADED.	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
07 Brake Condition		**الفرامل**
07.A Brake Pedal	SPONGY.	دواسة الفرامل
07.B Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		**ممتص الصدمات**
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		**المقود**
09.A Steering Boot	CUT .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		**الحاله الداخليه**
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
10.B Mirror	KNOB WORN OUT .	المرايا
10.C AC Condition	NOT COOLING.	المكيف
10.D Power Window Switch And Glass	FRONT RIGHT SIDE NOT WORKING.	مفتاح النافذه و الزجاج
10.E Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae