CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2972870
Transaction Date	12 Nov 2026, 10:26:09
Site Name	840 - Emirates Auctions
Transaction Number	27559981 (CC10008) (CC10011)



Vehicle Details

Chassis Number	SALGA2BU9M*******
Specification	GCC Specification
Make	Range Rover
Model	HSE
Model Year	2021
Color	White
Mileage	112441 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE,REAR RIGHT REPAINTED PORTION REPAIRED & FRONT LEFT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS ,POWER TRAIN GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED COVER PARTS MISSING ,CHECKED VISIBLE AREA ONLY	الارضية
01.F Bumper	MISALIGN MINOR SCRATCHES	دعامية
01.G Roof	PORTION REPAINTED	السقف
01.H Bonnet	REPAIRED REPAINTED,REFITTED	غطاء المحرك
01.I Trunk	PORTION REPAIRED REPAINTED,REFITTED,MISALIGN	صندوق
01.J Sign of front accident	FRONT ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.K Sign of side accident		وجود مؤشر لحادث في الجانب
01.L Sign of back accident		وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA /OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS GETTING MINOR RUSTY /OK	الحالة النظريه للمحرك
04 Transmission Condition		الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS GETTING FADED,RIGHT SIDE BRACKET DAMAGED REPAIRED	الاضاءة الرئيسية
07 Interior Condition		الحاله الداخليه
07.A AC Condition	OK	المكيف
07.B Dash Board	AIR BAG WAS DAMAGED ,LEATHER REPLACED	لوحة القياده
07.C Roof Ceiling	PORTION MINOR LOOSE	بطانه السقف
07.D Steering Wheel and control buttons	GETTING WORN OUT	عجلة القيادة وازرار التحكم
07.E Engine Start Button	REMOTE WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae