



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 Sep 2021, 14:18:51
Transaction Number	12749455 (CC10006)	Queue Number	312309



Chassis Number	JMYDRK9608J713896
Engine Number	
Vehicle Class	Car
Manufacturer	Mitsubishi
Model	Nativa
Model Year	2008
Color	Grey
Mileage	233397

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS , FLOORING, SUSPENTION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR RUST PROOFED	الارضية
01.F Bumper	REPAIRED & REPAINTED	دعامية
01.G Roof	REPAIRED & REPAINTED	السقف
01.H Bonnet	REPAIRED & REPAINTED	غطاء المحرك
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME RUST PROOFED	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED	كرسي
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير
05.A Gear Box	OK	الجير

DEFECT	REMARKS	
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2017 CRACKED & WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2017 CRACKED & WORN OUT	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	WORN OUT & BLADE RUSTY	اخرى
08 Lights		الاضاءة
08.A Head Light	OK	الاضاءة الرئيسية
08.B Other	OK	اخرى
08.C Indicator	REAR LEFT SIDE NOT WORKING	الاشارات
09 Brake Condition		الفرامل
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED, RUSTY	ازرع
11 Steering Condition		المقود
11.A Axle	BOOT CUT & LEAKING	اكسلات
12 Interior Condition		الاجزاء الداخلية
12.A Other	OK	اخرى
12.B Mirror	OK	المرآيا
12.C AC Condition	A/C NOT COOLING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.