





### Test Certificate

|                     |                          |                    |                 |
|---------------------|--------------------------|--------------------|-----------------|
| Site Number         | : 840-TASJEEL EM AUCTION | Plate Code         | : 0             |
| Transaction Number  | : 18781702               | Plate Category     | : PRIVATE       |
| Transaction Date    | : 18 DEC 2019 12:12:21   | Plate Number       | : 2704 EA       |
| Queue Number        | : 126452                 | Import Doc. Ref.   | :               |
| Chassis Number      | : 1N4AL21D48C172704      | Manufacturer/Model | : NISSAN/ALTIMA |
| Engine Number       | :                        | Model Year         | : 2008          |
| Vehicle Class       | : LIGHT VEHICLE          | Vehicle Color      | : WHITE         |
| Service / Indicator | : DSC AUCTION            |                    |                 |

### Statement of Vehicle Condition

| Defect                                     | Result                                | Remarks                      |
|--|---------------------------------------|------------------------------|
| AUTOMATIC TEST:                            |                                       |                              |
| 13 Brake System                            |                                       | الفرامل                      |
| 13.04 - Brake Test                         | Passed                                | فحص الفرامل                  |
| 14 Exhaust Gas Test                        |                                       | الغاز العادم والكربون        |
| 14.01 - Exhaust Gas Test                   | Passed                                | فحص الغاز العادم-الكربون     |
| VISUAL TEST:                               |                                       |                              |
| 01 Lights                                  |                                       | الانوار                      |
| 01.02 - Tail Lights                        | CRACK                                 | الانوار الخلفية              |
| 01.04 - Head Lights                        | FADED                                 | الانوار الامامية             |
| 02 Steering And Suspension System          |                                       | عجلة القيادة ونظام التوصيلات |
| 02.15 - Suspension Crack Or Bend, Bushes   | SUSPENSION BUSHES CRACK               | التوصيلات                    |
| 04 Tires Rims                              |                                       | الاطارات والعجلات            |
| 04.01 - Front Left And Right Hands Tires   | ALL TIRE DOT 2019                     | الاطارات الامامية            |
| 05 Body                                    |                                       | الهيكل                       |
| 05.01 - Rusty                              | UNDER BODY COMPONANTS PARTLY RUSTY    | الصدأ                        |
| 05.02 - Paint                              | SCRATCH & DENT ON BODY                | الصبغ                        |
| 05.07 - Floor                              | FLOOR REINFORCEMENT DENT              | الارضية                      |
| 06 General Items                           |                                       | الاشياء العامة               |
| 06.01 - Wiper Blades                       | WORN OUT                              | ماسحات الزجاج الامامي        |
| 06.12 - Seats Condition And Seats Fixing   | INTERIOR PARTLY WORN OUT              | المقاعد وحالتها وتثبيتها     |
| 07 Remarks                                 |                                       | ملاحظات                      |
| 07.04 - Others                             | 239757 KM                             | ملاحظات اخرى                 |
| 09 Auction                                 |                                       | الفحص الكامل                 |
| 09.02 - Need Wheel Alignment               | VEHICLE PULLING TO LEFT WHILE DRIVING | بحاجة الى ميزانية العجلات    |
| 09.06 - Chassis Ok                         | OK                                    | الشاصي جيد                   |
| 09.09 - Engine And Gear Box Performance Ok | OK                                    | فحص حالة الماكينة والجير     |
| 09.18 - A/C Not Cooling                    | AC NOT COOLING                        | عطل في المكيف                |

The Test Certificate Shows the test Result at the time of inspection only.



### Test Certificate

|                     |                          |                    |                 |
|---------------------|--------------------------|--------------------|-----------------|
| Site Number         | : 840-TASJEEL EM AUCTION | Plate Code         | : 0             |
| Transaction Number  | : 18781702               | Plate Category     | : PRIVATE       |
| Transaction Date    | : 18 DEC 2019 12:12:21   | Plate Number       | : 2704 EA       |
| Queue Number        | : 126452                 | Import Doc. Ref.   | :               |
| Chassis Number      | : 1N4AL21D48C172704      | Manufacturer/Model | : NISSAN/ALTIMA |
| Engine Number       | :                        | Model Year         | : 2008          |
| Vehicle Class       | : LIGHT VEHICLE          | Vehicle Color      | : WHITE         |
| Service / Indicator | : DSC AUCTION            |                    |                 |

Statement of Vehicle Condition