

Queue Number 2878087

Transaction Date 17 Oct 2026, 12:14:15

Site Name
840 - Emirates AuctionsTransaction Number
38305058 (CC10013) (CC10011)

Vehicle Details

Chassis Number	MR2KW9F30G*****
Specification	GCC Specification
Make	Toyota
Model	Yaris
Model Year	2016
Color	White
Mileage	284515 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE,REAR LEFT REPAINTED PORTION REPAIRED,FRONT LEFT REPAIRED REPAINTED & FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,DENTS SCRATCHES,PORTION RUSTY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUNNING BOARD BEND	الارضية
01.E Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.F Bonnet	REPAINTED REFITTED	غطاء المحرك
01.G Pillars	LEFT SIDE C/PILLAR REPAINTED PORTION REPAIRED	القوائم
01.H Trunk	REPAINTED PORTION REPAIRED,LUGGAGE SHADE MISSING	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME RADIATOR SUPPORT BULK HEAD REPAIRED ASSMEBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.J Sign of back accident	QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS BULK HEAD & REAR LEFT SIDE EXTENSION END OUTER SKIRT OPEN DETACHED	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET MUDDY , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	-------------------------------------	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	DIRTY,DRIVER SEAT PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY (LOW POWER)	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED EXPIRED	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2023 CRACK,RIGHT 2021 CRACK EXPIRED	الاطار الخلفي
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	WEAK	ممتص الصدمات
08.B Arms	ARM BUSHES DRY CRACK	ازرع
08.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	OK	المكيف
10.C Dash Board	RIGHT SIDE CUP HOLDER DAMAGED	لوحة القيادة
10.D Steering Wheel and control buttons	WORN OUT HORN NOT WORKING,AIRBAG UNIT LOOSE	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوى والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

